

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY State Hospital ADDRESS Phoenix BUILDING NO Butcher Shop
Feeling Room

DATE 2/4/57 AGENCY ADMINISTRATOR Dr. Samuel Wick INSPECTOR R. R. Johnson

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C	X			X		
EXTERIOR WALLS	Frame and Stucco		X			X	
EXTERIOR PAINT				X			X
ROOF	M/S		X				X
INTERIOR WALLS	15# Felt. Plaster	(1)X		(2)X	(1)X		(2)X
FLOORS	Conc.	X			X		
CEILING	Celotex			X			X
INTERIOR PAINT							
WINDOWS	S/S		X			X	
DOORS	Wood			X			X
SCREENING	Steel			X		X	
LOCKS	O. K.						
ELECTRICAL WIRING	Conduit			X		X	
ELECTRICAL FIXTURES							
PLUMBING FIXTURES	China		X			X	
SANITATION	E. I.	X			X		
FIRE EXTINGUISHERS	CO ₂						
FIRE HOSES	None						
EMERGENCY EXITS	O. K.						
FIRE NOTICES	None						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: Requires ext. paint evidence of roof leaks.
Vegetable cooling room: ref'r. lines rusted badly. Compressor room: Replace romex
meat locker - Ammonia lines badly rusted. North shed supports and framing rusting.

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY State Hospital ADDRESS Phoenix BUILDING NO **Mattness Shop**
 DATE 2/4/57 AGENCY ADMINISTRATOR Dr. Samuel Wick INSPECTOR R. R. Johnson

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C			X	X		
EXTERIOR WALLS	Conc. and Frame		X			X	
EXTERIOR PAINT				X			X
ROOF	M/S		X			X	
INTERIOR WALLS	Sheetrock	X				X	
FLOORS	Conc.						
CEILING	None (Exposed sheathing)	X			X		
INTERIOR PAINT			X			X	
WINDOWS	W/S and S/S	X			X		
DOORS	Wood	X			X		
SCREENING	Steel	X			X		
LOCKS	O. K.						
ELECTRICAL WIRING	Conduit	X			X		
ELECTRICAL FIXTURES	Floor.			X		X	
PLUMBING FIXTURES	China	X				X	
SANITATION	C. I.	X			X		
FIRE EXTINGUISHERS	CO ₂ plus S. A.			X		X	
FIRE HOSES	None						
EMERGENCY EXITS	None						
FIRE NOTICES	O. K.						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: Foundation requires fill on southside to prevent water intrusion. 5# CO₂ (11-22-55) recharge. Water heater and coffee maker should be in enclosed room away from inflammable material.

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY State Hospital ADDRESS Phoenix BUILDING NO. Motor Shop, Garage and Paint Shop
 DATE 2-1-57 AGENCY ADMINISTRATOR Dr. Samuel Wick INSPECTOR R. R. Johnson

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C	X			X		
EXTERIOR WALLS	Brick	X			X		
EXTERIOR PAINT			X				X
ROOF	M/S	X			X		
INTERIOR WALLS	None						
FLOORS	Conc.		X				X
CEILING	None						
INTERIOR PAINT			X				X
WINDOWS	S/S			X			X
DOORS	Wood						
SCREENING	None						
LOCKS	O. K.						
ELECTRICAL WIRING	Conduit	X			X		
ELECTRICAL FIXTURES	Inc.	X			X		
PLUMBING FIXTURES	China	X				X	
SANITATION	C. I.	X			X		
FIRE EXTINGUISHERS	CO ₂	X			X		
FIRE HOSES	1 1/2"	X			X		
EMERGENCY EXITS	O. K.						
FIRE NOTICES	O. B.						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: Exterior and interior walls require pointing.

Replace 40 panes glass.

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY	ADDRESS	BUILDING NO. <i>Warehouse</i>					
DATE	AGENCY ADMINISTRATOR	INSPECTOR					
ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C	X			X		
EXTERIOR WALLS	Brick	X			X		
EXTERIOR PAINT		X			X		
ROOF	Flu	X			X		
INTERIOR WALLS	Plaster	X			X		
FLOORS	Conc.	X			X		
CEILING	Celotex Sheathing	X			X		
INTERIOR PAINT		X			X		
WINDOWS	Glass Block	X			X		
DOORS	Wood	X			X		
SCREENING	None						
LOCKS	O. K.						
ELECTRICAL WIRING	Conduit	X			X		
ELECTRICAL FIXTURES	Inc.	X			X		
PLUMBING FIXTURES	China	X			X		
SANITATION	C. I.	X			X		
FIRE EXTINGUISHERS	SA Co. Sprinkler	X			X		
FIRE HOSES	1 1/2"	X			X		
EMERGENCY EXITS	None						
FIRE NOTICES	O. K.						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: *None.*

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY	ADDRESS	BUILDING NO. D					
DATE	AGENCY ADMINISTRATOR	INSPECTOR					
ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C	X			X		
EXTERIOR WALLS	R/C and Brk. ctn. Walls		X			X	
EXTERIOR PAINT			X			X	
ROOF	Blu	X			X		
INTERIOR WALLS	Brick		X			X	
FLOORS	Cong. and Asp. Tile		X		X		
CEILING	Cong.		X			X	
INTERIOR PAINT			X				X
WINDOWS	S/S	X			X		
DOORS	Wood		X			X	
SCREENING	Bronze		X			X	
LOCKS	O. K.						
ELECTRICAL WIRING	Conduit	X			X		
ELECTRICAL FIXTURES	Inc. and Fluor.			X		X	
PLUMBING FIXTURES	China	X				X	
SANITATION	C. I.	X			X		
FIRE EXTINGUISHERS	S. A.	X			X		
FIRE HOSES	1 1/2"	X			X		
EMERGENCY EXITS	O. K.						
FIRE NOTICES	O. K.						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: (To be reconditioned) None.

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY State Hospital ADDRESS Phoenix BUILDING NO. G

DATE 2/4/57 AGENCY ADMINISTRATOR Dr. Samuel Wick INSPECTOR R. R. Johnson

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C	X			X		
EXTERIOR WALLS	Brick and R.Q.	X			X		
EXTERIOR PAINT		X			X		
ROOF	Blu. and chat.	X			X		
INTERIOR WALLS	St'l. and plaster		X		X		
FLOORS	Conc. and Asp.	X			X		
CEILING	St'l and Plaster (Acoustic)			X		X	
INTERIOR PAINT	Latex Base		X		X		
WINDOWS	Alum sash	X			X		
DOORS	Wood and Alum.	X			X		
SCREENING							
LOCKS	O. K.						
ELECTRICAL WIRING	Cond.						
ELECTRICAL FIXTURES	Inc.	X			X		
PLUMBING FIXTURES	China	X			X		
SANITATION	C.I.	X			X		
FIRE EXTINGUISHERS	S.A. and CO ₂	X			X		
FIRE HOSES							
EMERGENCY EXITS	O. K.						
FIRE NOTICES	O. K.						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: Asp. base badly deteriorated - replace with rubber. - Shower rooms, paint teteriorated - Light covers rusting - Stairways very slippery - require anti-skid covering.

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY	ADDRESS	BUILDING NO. <i>Rec. E</i>					
DATE	AGENCY ADMINISTRATOR	INSPECTOR					
ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C	X			X		
EXTERIOR WALLS	Brick and Stucco		X			X	
EXTERIOR PAINT			X				X
ROOF	Tile (I.C.)	X			X		
INTERIOR WALLS	Frame Plaster		X				X
FLOORS	Conc. and Lino.	X			X		
CEILING	Acoustic		X			X	
INTERIOR PAINT		X			X		
WINDOWS	S/S	X			X		
DOORS	Wood	X			X		
SCREENING	St'l.	X			X		
LOCKS	O. K.						
ELECTRICAL WIRING	Cond.	X			X		
ELECTRICAL FIXTURES	Inc.	X			X		
PLUMBING FIXTURES	China	X				X	
SANITATION	C. I.	X			X		
FIRE EXTINGUISHERS	S. A. and CO ₂	X			X		
FIRE HOSES	1 1/2"	X			X		
EMERGENCY EXITS	O. K.						
FIRE NOTICES	O. K.						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: Dayroom requires chair rail.

STATE PLANNING AND BUILDING COMMISSION
BUILDING INSPECTION REPORT

AGENCY	ADDRESS	BUILDING NO. <i>Rec. W</i>					
DATE	AGENCY ADMINISTRATOR	INSPECTOR					
ITEM	MATERIAL	MAINTENANCE			CONDITION		
		Good	Fair	Poor	Good	Fair	Poor
FOUNDATION	R/C	X			X		
EXTERIOR WALLS	Brick and Stucco		X			X	
EXTERIOR PAINT			X				X
ROOF	Tile (Terra Cotta)	X			X		
INTERIOR WALLS	Frame Plaster		X			X	
FLOORS	Conc. and Lino.	X			X		
CEILING	Acoustic		X			X	
INTERIOR PAINT		X			X		
WINDOWS	S/S	X			X		
DOORS	Wood	X			X		
SCREENING	St'l/	X			X		
LOCKS	O. K.						
ELECTRICAL WIRING	Conduit.	X			X		
ELECTRICAL FIXTURES	Inc.	X			X		
PLUMBING FIXTURES	China	X				X	
SANITATION	C. I.	X			X		
FIRE EXTINGUISHERS	S. A. and CO ₂	X			X		
FIRE HOSES	1 1/2"	X			X		
EMERGENCY EXITS	O. K.						
FIRE NOTICES	O. K.						
WATER PRESSURE	O. K.						

REMARKS AND RECOMMENDATIONS: Chair rail in dayroom areas.
