

STATE PLANNING AND BUILDING COMMISSION

BUILDING INSPECTION REPORT

Cowboy Building-Fort Misery-Schoolhouse

AGENCY Prescott Hist. Society ADDRESS Prescott BUILDING NO.

DATE 4-26-63 AGENCY ADMINISTRATOR Mrs. Knight INSPECTOR Nielsen

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		GOOD	FAIR	POOR	GOOD	FAIR	POOR
FOUNDATION	Concrete	X			X		
EXTERIOR WALLS	Chinked Logs	X			X		
EXTERIOR PAINT	Stain	X			X		
ROOF	Wood shakes	X			X		
INTERIOR WALLS	Same as exterior	X			X		
FLOORS	Concrete	X			X		
CEILING	Board	X			X		
INTERIOR PAINT	Stain	X			X		
WINDOWS	Wood Casement	X			X		
DOORS	Wood	X			X		
SCREENING	None						
LOCKS	Padlocks	X			X		
ELECTRICAL WIRING	Romex	X			X		
ELECTRICAL FIXTURES							
PLUMBING FIXTURES	None						
SANITATION	None						
FIRE EXTINGUISHERS	CO2	X			X		
FIRE HOSES	None						
EMERGENCY EXITS	None						
FIRE NOTICES	None						
WATER PRESSURE	None						

UTILIZATION: Cowboy Bldg: Storage & display of cowboy tools & equipment

Ft. Misery : Model of frontier law office

Schoolhouse : Frontier school

REMARKS AND RECOMMENDATIONS: Cowboy Bldg: Inadequate display and poor appearance; needs display cases & racks.

STATE PLANNING AND BUILDING COMMISSION

BUILDING INSPECTION REPORT

Outdoor
displ.

AGENCY Prescott Hist. Society ADDRESS Prescott BUILDING NO.
 DATE 4-26-63 AGENCY ADMINISTRATOR Mrs. Knight INSPECTOR Nielsen

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		GOOD	FAIR	POOR	GOOD	FAIR	POOR
FOUNDATION	Concrete	X			X		
EXTERIOR WALLS	Concrete Block & wood	X			X		
EXTERIOR PAINT	Stain	X			X		
ROOF	Tar & sheathing	X			X		
INTERIOR WALLS	Same as exterior	X			X		
FLOORS	Concrete	X			X		
CEILING	None						
INTERIOR PAINT	Stain	X			X		
WINDOWS	Wood & steel casement	X			X		
DOORS	Wood	X			X		
SCREENING	Metal	X			X		
LOCKS	Padlocks & tumblers	X			X		
ELECTRICAL WIRING	Romex	X			X		
ELECTRICAL FIXTURES		X			X		
PLUMBING FIXTURES	None						
SANITATION	None						
FIRE EXTINGUISHERS	4 CO ₂	X			X		
FIRE HOSES	None						
EMERGENCY EXITS	None						
FIRE NOTICES	None						
WATER PRESSURE	None						

UTILIZATION: Display of historical vehicles & model of early-day area mining operation.

REMARKS AND RECOMMENDATIONS: Front is open but heavily screened; should be enclosed to prevent weather entry. (This was recommended by Planning & Building Commission to Legislature in Jan. 1963)

STATE PLANNING AND BUILDING COMMISSION

BUILDING INSPECTION REPORT

AGENCY Prescott Hist. Society		ADDRESS Prescott	Main Museum BUILDING NO.					
DATE 4-26-63	AGENCY ADMINISTRATOR Mrs. Knight	INSPECTOR Nielsen						
ITEM	MATERIAL	MAINTENANCE			CONDITION			
		GOOD	FAIR	POOR	GOOD	FAIR	POOR	
FOUNDATION	Concrete	X			X			
EXTERIOR WALLS	Native Stone	X			X			
EXTERIOR PAINT	None							
ROOF	Asphalt shingles over wood (1955)	X			X			
INTERIOR WALLS	Stone	X			X			
FLOORS	Stone	X			X			
CEILING	None							
INTERIOR PAINT	Stain & Varnish	X			X			
WINDOWS	Wood & Aluminum casement	X			X			
DOORS	Aluminum	X			X			
SCREENING	Metal	X			X			
LOCKS	Tumbler	X			X			
ELECTRICAL WIRING	Conduit	X			X			
ELECTRICAL FIXTURES	Hanging	X			X			
PLUMBING FIXTURES	None							
SANITATION	None							
FIRE EXTINGUISHERS	2 - CO ₂	X			X			
FIRE HOSES	Exterior *							
EMERGENCY EXITS	None							
FIRE NOTICES	None							
WATER PRESSURE	Good							

UTILIZATION: Display historical artifacts, club meetings, office & manuscript storage(vault), newspaper storage vault, apartment for assistant custodian.

REMARKS AND RECOMMENDATIONS: * Small (3/4") supply line to grounds fire hoses gives inadequate fire protection. Fireplace (stone) lintel cracked. Termite problem could develop in exposed wood pole joists & beams. One main beam is separated from its anchor in stone wall.

STATE PLANNING AND BUILDING COMMISSION

BUILDING INSPECTION REPORT

AGENCY Prescott Hist. Society ADDRESS Prescott Old Gov's BUILDING NO. Mansie

DATE 4-26-63 AGENCY ADMINISTRATOR Mrs. Knight INSPECTOR Nielsen

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		GOOD	FAIR	POOR	GOOD	FAIR	POOR
FOUNDATION	Undetermined						
EXTERIOR WALLS	Chinked logs		X			X	
EXTERIOR PAINT	None		X			X	
ROOF	Wood shingles			X			X
INTERIOR WALLS	Same as Exterior		X			X	
FLOORS	Wood & Concrete		X			X	
CEILING	Wood			X			X
INTERIOR PAINT	Stain		X			X	
WINDOWS	Wood casement		X			X	
DOORS	Wood		X			X	
SCREENING	Steel mesh	X			X		
LOCKS	Tumbler & Padlock	X			X		
ELECTRICAL WIRING	Romex and insulated wire		X			X	
ELECTRICAL FIXTURES	Ancient		X			X	
PLUMBING FIXTURES	None						
SANITATION	None						
FIRE EXTINGUISHERS	2 - CO2	X			X		
FIRE HOSES	None *						
EMERGENCY EXITS	None						
FIRE NOTICES	None						
WATER PRESSURE	None *						

UTILIZATION: Display of historical artifacts (Sharlot Hall collection), simulation of some rooms per use 100 years ago.

REMARKS AND RECOMMENDATIONS: * Small 3/4 inch line & low water pressure for exterior hoses inadequate for proper fire protection. Building will be repaired with \$9,646 appropriation for 1963-64 fiscal year.