

STATE PLANNING AND BUILDING COMMISSION

BUILDING INSPECTION REPORT

AGENCY AGRICULTURE & HORTICULTURE - ENTOMOLOGIST

ADDRESS Cameron, Arizona

BUILDING NO. Cameron Border Inspection Stn.

DATE Aug 7, 1963

AGENCY
ADMINISTRATOR

INSPECTOR /
VLNielsen

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		GOOD	FAIR	POOR	GOOD	FAIR	POOR
FOUNDATION	Concrete	X			X		
EXTERIOR WALLS	Steel	X			X		
EXTERIOR PAINT	?	X			X		
ROOF	Steel/Caulked	X			X		
INTERIOR WALLS	Steel	X			X		
FLOORS	Concrete/Asbestos Tile	X			X		
CEILING	Steel	X			X		
INTERIOR PAINT	?	X			X		
WINDOWS	Steel Frame	X			X		
DOORS	Steel	X			X		
SCREENING	None						
LOCKS	Deadlock	X			X		
ELECTRICAL WIRING	Conduit	X			X		
ELECTRICAL FIXTURES	Fluorescent/Incandescent	X			X		
PLUMBING FIXTURES	China	X			X		
SANITATION	?	X			X		
FIRE EXTINGUISHERS	Dry Chemical (New)	X			X		
FIRE HOSES	None						
EMERGENCY EXITS	None						
FIRE NOTICES	None						
WATER PRESSURE	58 psi @ Wellhead	X			X		

UTILIZATION: Average 1400 cars/day in summer.

REMARKS AND RECOMMENDATIONS: Two small cracks in concrete island extension.
Complete indoor closet for brooms, mops, hoses, etc.
Canopy vibrates & sways in winds 40-50 mph.

Station crew installing its own trailer park at rear with 5 spaces, septic tank, well & electricity.

Building neat and clean.