

STATE PLANNING AND BUILDING COMMISSION

BUILDING INSPECTION REPORT

BORDER INSPECTION STATION

AGENCY AG. & HORT. ADDRESS Alt. 80 U.S. - Yuma, Arizona BUILDING NO.

DATE April 3, 1963 AGENCY ADMINISTRATOR W. T. Mendenhall INSPECTOR Nielsen

ITEM	MATERIAL	MAINTENANCE			CONDITION		
		GOOD	FAIR	POOR	GOOD	FAIR	POOR
FOUNDATION	Wood sill		X			X	
EXTERIOR WALLS	Plaster/frame		X			X	
EXTERIOR PAINT	Grey			X			X
ROOF	Wood sheathing, steel truss; tile edging		X			X	
INTERIOR WALLS	Plaster/frame		X			X	
FLOORS	Wood on concrete	X			X		
CEILING	Plaster	X			X		
INTERIOR PAINT				X			X
WINDOWS	Steel sash	X			X		
DOORS	Wood (4)		X			X	
SCREENING	None						
LOCKS			X			X	
ELECTRICAL WIRING			X			X	
ELECTRICAL FIXTURES			X			X	
PLUMBING FIXTURES			X			X	
SANITATION		X			X		
FIRE EXTINGUISHERS	None						
FIRE HOSES	None						
EMERGENCY EXITS	Three wooden doors		X			X	
FIRE NOTICES	None						
WATER PRESSURE		X			X		

UTILIZATION: AGRICULTURE INSPECTION OF MOTOR VEHICLES. Building not used by public except for occasional interviews. Closed at night.

REMARKS AND RECOMMENDATIONS: Building constructed in 1923 when old highway bridge built.